

MAC 600 E NT™

Software

Main CPU

2002-04-08

ID: 2123 User support

Version 1.3, 2001-10-17

- Removes the fan speed regulation feature to prevent potential overheating.
- Increases current to pan/tilt motors in studio mode to prevent step-loss when using the 18° long front

Download MU3 file

Version 1.2, 2001-06-25

- Fixes a bug that could cause pan/tilt not to react to single step change with the LightJockey controller.
-

Version 1.1 (not released)

Version 1.0, 2001-03-19

- Improves color mixing acceleration and quieter performance
- Bug fix: CMY and CTC flags hit switches in test sequence (TSEQ)