

MAC 700 WASH™

Software

Main CPU

2007-12-12

ID: 5094 User support

Version 1.3.0, 2007-12-04

- Bugfix: color blackout before resetting shutter corrected
- CMY blackout while moving removed
- Fixture now displays COLD and DMX disabled when ambient temp. below -20° C (-4° F)
- DMX lamp on now delayed for 10 sec. after DMX signal received

Download MU3 file

Version 1.2.0, 2006-06-08

- Initial release

Download MU3 file